Change history GrowControl PowerExtender 4+ "Betaversion"

There are usually two firmware versions for a controller.

Beta version: New features - New bugs

Here the newest features are included. The probability for bugs is higher in this version.

The file name or version number of a beta version ends with the letter "b". (e.g. fw504500000b.bin)

Stable version:

This version has been extensively tested. The individual functions have usually passed through the beta version before.

The file name or version number of a stable version ends with the letter "s". (e.g. fw504500000s.bin)

Feedback:

Please give us feedback about your experience with this version or about our products in general.

Both positive and negative feedback is very important for us to become even better.

Please also feel free to give us feedback on how interesting or important a newly added feature or change is to you, or what you would like to see in the future.

If your feedback relates to a specific product or version, please include the firmware version number, product name and, if possible, the serial number found on the bottom of the unit.

If it is an error description, please describe the error and the circumstances under which it occurs as precisely as possible.

This document lists chronologically the changes that have a particular impact on users.

18.02.2023 – 5046.0.00.03b (file name: fw504600003b.bin)

- **Correction: Wrong file for 5046.0.00.02b released**

17.02.2023 – 5046.0.00.02b (file name: fw504600002b.bin)

- **Additional Multi Out Functions from GrowBase Pro Version ...15b**
  To make the new functions (Interval Timer, Event, Always ON) available for PowerExtender 4+, an update to version 5046.0.00.02b must be performed.

  Attention! After the update, the PowerExteder 4+ is no longer compatible with older firmware versions for GrowBase Pro.

Firmware GrowBase Pro	Firmware PowerExtender 4+	Funktion
from 15b	from 2b	OK, full functional
from 15b	smaller 2b	OK, new functions missing
smaller 15b	smaller 2b	OK, new functions missing
smaller 15b	from 2b	**Not working**

  Of course, after installing this version, it is possible to install the older version again.

26.03.2021 – 5046.0.00.01s (file name: fw504600001s.bin)

  Transfer as stable version

25.01.2021 – 5046.0.00.00b (file name: fw504600000b.bin)

  Firs release

PowerExtender 4+ 5046.0.00.02b

GROWCONTROL